E03 Comigurati	on Changeaqu	iesi,		P	age 1 of Pages
CCR No. タター クロタル Logged Da		Date 1/23/98	Rev Request T		ype CCR
Priority Routine	X Urgent	Emergency	Affected Release	~	Change Class $/\mathcal{N}$
Title (description)Rack/Power changes in 1057					
Documents Affected ハノイ	i		Source Nos (RID, Tech Reference	NCR, Action Ite	em, GSFC CCR, etc.) or
RTM Change Start New Baseline					
Problem We are out of rack space and power in 1057. We are planning to move all of the non-FOS NetApps into this room in order to facilitate out of band backups. There are not enough power receptacles or racks to accommodate the additional machines.					
Proposed Solution We want to add 4 new racks and 6 new 30 amp receptacles to the room. These racks will parallel the outside hall. The power receptacles will be located underneath the racks. The installers should see Glenn Johnson or Borris Crosby for further information about the desired locations.					
					
Impact Analysis: Organizations Affected: Procurement x Science Off	_	Contracts	ECS Chief Eng Rel. A Sys. Eng	FOS Rel. C Sys Verf Acpt	M&O SCDO Arch
Cost:	None 🗌	Small x (Not exceeding \$100.000)	Medium	Large	-
Schedule:	None	Other			
Additional LOC		Man-Months			
Materials		117	A_{λ}		10 5
Originator Glenn R Jo	Office Manager	Signature	Col	_	/23/98 Date
Disposition	Approved [Approved w/Comn	nent For	vard 🗍	Disapproved
Comments:		, ,			Ц
	CCB Chairperson	Wa 12	Come		1/26/28 Date

ORIGINAL

CM01OC96

ECS

en esp